

TEMP. (Pt 100 ohm) TRANSMITTER

Model : TR-TMP1A4

ISO-9001, CE, IEC1010



Pt 100 ohm
Temp. probe
(Optional)



LUTRON ELECTRONIC

The Art of Measurement

Temperature (Pt 100 ohm) TRANSMITTER

Model : TR-TMP1A4

Measure Range	-100 °C to 400 °C
Output	4 - 20 mA
	-100 °C = 4 mA 0 °C = 7.2 mA 400 °C = 20 mA
External Adjustment	ZERO VR SPAN VR
Power Supply	90 - 260 ACV 50 Hz/60 Hz
Operation Temperature	0 - 50 °C 32 - 122 °F
Operation Humidity	Less than 80 %RH
Accessory Included	Pt 100 ohm probe is optional.
Optional Accessories	Pt 100 ohm temperature probe : TP-100
Mounting	Din rail or Wall
Case	ABS plastic
Others	Four wires connection

* Appearance and specifications listed in this brochure are subject to change without notice.

0811-TRTEMP1A4